



e²200.30

INSTALLATION PLAN

FRONT






SIDE



TOP



WHAT YOU NEED

Electrical cable + industrial plug			
	V.230/1/50-60Hz	V.230/3/50-60Hz	V.400/3N/50-60Hz
	n/a	46 Amps	26,5 Amps
Total power required	n/a	16,1 kW	16,1 kW
Differential magnetothermal switch	n/a	Idn = 0.03 Amps	Idn = 0.03 Amps
Ducting	n/a	Ø75 mm, 90 m ³ /h	Ø75 mm, 90 m ³ /h
Clearance around the ironer	back: 400 - right: 650 mm - left: not needed		