



# INSTALLATION PLAN


## FRONT






## TOP



## INSTALLATION PLAN



## WHAT YOU NEED

Electrical cable + industrial plug			
	V.230/1/50-60Hz	V.230/3/50-60Hz	V.400/3N/50-60Hz
	n/a	102 Amps	59 Amps
Total power required	n/a	40,6 kW	40,6 kW
Differential magnetothermal switch	n/a	I <sub>dn</sub> = 0.03 Amps	I <sub>dn</sub> = 0.03 Amps
Ducting	n/a	Ø76 mm, 405 m <sup>3</sup> /h	Ø76 mm, 405 m <sup>3</sup> /h
Clearance around the ironer	back: 500 mm - right: 500 mm - left: 500 mm		